

BEKOTAŞ CELULOSIC THINNER



Product Code: 340

Product Description

- It is a paint with Hydrocarbon resin and containing aluminum pigments. Its colour is aluminum gray. Has up to 200 ° C heat resistant, quick-drying, highly adhesive and gives the appearance of aluminum.

Application

- It can be used in all kinds of hardware, chimney, stove and exhaust pipes can be used safely.
- Application surface moisture, dirt, rust and old paint from the remains should be thoroughly cleaned and sanded. Products are designed to be ready for use. Is applied without thinning to single layer with by brush, roller or spray gun. If you need to recoat; must wait an hour between coats.
- Paint must be thoroughly mixed before use. Applications must be between 5-35 ° C at an ambient temperature. After each application; brush or roller should be cleaned with thinner.
- The surface where Bekostar Aluminium Metal Painting applied should be protected for 24 hours from physical and chemical factors. Definitely; do not

Usage

- Bekotaş Cellulosic Thinner



Technical Specifications:

Density

- 0.86 ± 0.05 g/ml

Brightness Point

- >38 °C

Connective Type

- Hydrocarbon resin

Solid Weight

- (%) : 16 ± 1

Density

- 0.86 ± 0.05 g/ml

Covering Capacity

- Theoretical:
12 m² / lt (20 µ dry film thickness)
Practical:
0,100 - 0,110 lt/m² (single layer)
0,090 - 0,100 kg/m² (single layer)

Danger Sign

- F: Flammable
Xn: Harmful

Risk Situations

- R 11: Highly flammable
R 20/21/22: Is harmful to health, if swallowed or inhaled.

Viscosity

- (sn / F4) (25 °C) : 10 - 15

Brightness

- (60° - Gloss) : Semi Mat

Bright Point

- (°C) : <21

Drying Time

- (20° C) : 15-20 minutes.

Thinning Rate

- Unthinned

Safety Warnings

- S2 Keep out of the reach of children.
S 3 / 7 / 9: Keep bucket closed, in a cool and well-ventilated place.

Safety Recommendations

- S16: Keep out from sources of ignition. No smoking.
S 24 / 25: Avoid contact with eyes and skin.
S 29: Do not discharge into drains or water courses.
S 46: If swallowed, seek medical advice immediately, and show the container or label.
S 51: Use only in well-ventilated areas